



---

## **Alert:**

Another Imperial Oil spill – Incident occurred on Dec 4<sup>th</sup> at the N08 pad. Steam and Bitumen has been released through misting, effecting the lease pad and surrounding area. CLFN is working with the Alberta Energy Regulator, as well as with Imperial Oil to gather more information on the incident and remediation strategy.

CLFN staff, members and leaders have had a limited tour of the site. Imperial estimates that less than one barrel of bitumen and an unknown volume of water migrated off-site. The Lands and Resources Department can neither confirm nor refute these estimates. Further, the Lands and Resources Department cannot yet comment on the degree to which the surrounding area was impacted. The spill released less than H65 pad because pressures in the well were lower so less came out and didn't spread as far.

More information to follow.